


# AIRPORT DIAGRAM

FARMINGTON/ FOUR CORNERS RGNL (FMN)  
AL-493 (FAA) FARMINGTON, NEW MEXICO



01020 JUN 03 01.01010 MAY 2010 90 '1-L-W-S

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.  
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

SW-1, 06 MAY 2010 to 03 JUN 2010

# AIRPORT DIAGRAM

FARMINGTON, NEW MEXICO  
FARMINGTON/ FOUR CORNERS RGNL (FMN)